


Bryant Park Club



| Product No. | Dimensions | Fabric \$ | | | | | Leather \$ | | | | |
|-------------|----------------|-----------|------|-----|------|-----|------------|-----|------|-----|------|
| TDB1 | 33w | COM | 2386 | F6 | 3035 | F12 | 3668 | COL | 2744 | L6 | 5714 |
| | 28.3d | F1 | 2755 | F7 | 3112 | F13 | 3822 | L1 | 4031 | L7 | 6209 |
| | 27h | F2 | 2799 | F8 | 3200 | F14 | 3992 | L2 | 4229 | L8 | 6803 |
| | 16.8sh | F3 | 2848 | F9 | 3299 | F15 | 4185 | L3 | 4526 | L9 | 7595 |
| | 27ah | F4 | 2903 | F10 | 3409 | F16 | 4405 | L4 | 4823 | L10 | 8486 |
| | 5.5 yds, 99 sf | F5 | 2964 | F11 | 3530 | F17 | 4647 | L5 | 5219 | L11 | 9476 |

Metal legs have an MRBS Resin Brushed Steel finish.


Bryant Park Settee



| | | | | | | | | | | | |
|------|-----------------|-----|------|-----|------|-----|------|-----|------|-----|-------|
| TDB2 | 50w | COM | 2846 | F6 | 3731 | F12 | 4594 | COL | 3273 | L6 | 7323 |
| | 28.3d | F1 | 3349 | F7 | 3836 | F13 | 4804 | L1 | 5028 | L7 | 7998 |
| | 27h | F2 | 3409 | F8 | 3956 | F14 | 5036 | L2 | 5298 | L8 | 8808 |
| | 16.8sh | F3 | 3476 | F9 | 4091 | F15 | 5299 | L3 | 5703 | L9 | 9888 |
| | 27ah | F4 | 3551 | F10 | 4241 | F16 | 5599 | L4 | 6108 | L10 | 11103 |
| | 7.5 yds, 135 sf | F5 | 3634 | F11 | 4406 | F17 | 5929 | L5 | 6648 | L11 | 12453 |

Metal legs have an MRBS Resin Brushed Steel finish.
Directional upholsteries may require railroading or additional seams on settees and sofas.

Bryant Park Sofa



| | | | | | | | | | | | |
|------|-----------------|-----|------|-----|------|-----|------|-----|------|-----|-------|
| TDB3 | 70w | COM | 3147 | F6 | 4268 | F12 | 5361 | COL | 3619 | L6 | 8749 |
| | 28.3d | F1 | 3784 | F7 | 4401 | F13 | 5627 | L1 | 5842 | L7 | 9604 |
| | 27h | F2 | 3860 | F8 | 4553 | F14 | 5921 | L2 | 6184 | L8 | 10630 |
| | 16.8sh | F3 | 3945 | F9 | 4724 | F15 | 6254 | L3 | 6697 | L9 | 11998 |
| | 27ah | F4 | 4040 | F10 | 4914 | F16 | 6634 | L4 | 7210 | L10 | 13537 |
| | 9.5 yds, 171 sf | F5 | 4145 | F11 | 5123 | F17 | 7052 | L5 | 7894 | L11 | 15247 |

Metal legs have an MRBS Resin Brushed Steel finish.
Directional upholsteries may require railroading or additional seams on settees and sofas.

Bryant Park Club, Disc Base



| | | | | | | | | | | | |
|-------------------|----------------|-----|------|-----|------|-----|------|-----|------|-----|-------|
| TDB1F (Fixed) | 33w | COM | 3410 | F6 | 4059 | F12 | 4692 | COL | 3922 | L6 | 6892 |
| | 28.3d | F1 | 3779 | F7 | 4136 | F13 | 4846 | L1 | 5209 | L7 | 7387 |
| | 28.2h | F2 | 3823 | F8 | 4224 | F14 | 5016 | L2 | 5407 | L8 | 7981 |
| | 18sh | F3 | 3872 | F9 | 4323 | F15 | 5209 | L3 | 5704 | L9 | 8773 |
| | 28.2ah | F4 | 3927 | F10 | 4433 | F16 | 5429 | L4 | 6001 | L10 | 9664 |
| | 5.5 yds, 99 sf | F5 | 3988 | F11 | 4554 | F17 | 5671 | L5 | 6397 | L11 | 10654 |
| TDB1B (Swivel) | 33w | COM | 3523 | F6 | 4172 | F12 | 4805 | COL | 4051 | L6 | 7021 |
| | 28.3d | F1 | 3892 | F7 | 4249 | F13 | 4959 | L1 | 5338 | L7 | 7516 |
| | 28.2h | F2 | 3936 | F8 | 4337 | F14 | 5129 | L2 | 5536 | L8 | 8110 |
| | 18sh | F3 | 3985 | F9 | 4436 | F15 | 5322 | L3 | 5833 | L9 | 8902 |
| | 28.2ah | F4 | 4040 | F10 | 4546 | F16 | 5542 | L4 | 6130 | L10 | 9793 |
| | 5.5 yds, 99 sf | F5 | 4101 | F11 | 4667 | F17 | 5784 | L5 | 6526 | L11 | 10783 |

Disc base and column have a MRBS Resin Brushed Steel finish.
The swivel mechanism is self-aligning back to center.

Shipping address for COM/COL materials and memo samples:
TUOHY Furniture Corporation, Upholstery Receiving Dept, 13715 S Western Ave, Gardena, CA 90247



Please provide tagging information as needed for your project.